



NOTICE

Dryer Vent Wizard has been in the Crescent Springs Condo community to clean all dryer vents from the outside. In order to do a more complete and thorough cleaning it would be advisable that your vent also be inspected from the inside of your laundry room.

As you may know Dryers are becoming one of the leading causes of residential fires. One of the most important parts of your venting system is the piece of vent pipe which attaches your dryer to the wall – this is called the **transition piece**. It is critical to the safety of you and your neighbors that this transition be composed of non-combustible material or solid metal – **not plastic or flexible foil**. Since we did the cleaning from the outside only, we did not have a chance to inspect your transition.

If you would like to have your transition inspected to see if it needs replacing please call **502-235-0734** to schedule an appointment. At this time we can also inspect and clean the interior of your dryer if there is excessive lint build up. We can also inspect and replace your washing machine hoses if they have not been replaced in the last 3-5 years as manufacturers suggest. By having this done, you greatly diminish the risk of fire and water damage for you and your neighbors.

Thank you for allowing us to serve your community,

Keith O'Loane, owner
Dryer Vent Wizard of Kentuckiana
502-235-0734
www.drverventwizard.com